ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	15	T Dasarahalli
Street ID	**Street Name**	**Significant Landmark**
W0135, W0288, W0124, I0133, W0284, W0140, W0148, W	NA, Vinayaka Lyt 4th Crs, 3rd Crs, 3rd Crs Lakshmi Sagar Lyt, 3rd A Crs Maheshwari Nagar	Dasarahalli
Segment No.	**Total Length (m)**	
15/C-W0135/S034858	563.58	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	563.58	77.514974	13.044575	77.518246	13.048521	Coconut Garden SWD	Pipeline road

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements of Re Asphalting Dasarahalli Main road & Other roads S Ramesh, Ganesha Saw Mill, Kempegowda nagara and Maheshwari Nagara roads, Construct	30000000	2018-19
Year	**Type of Work**	**Other Work Type**
2018 - 2019	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Tender		015-18-000007
Work Order No.	**Work Order Date**	**Period of Extention**
305/18-19	02/02/2019	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
02/02/2019	01/02/2020	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M S Venkatesh		21915877.00
Phone No.	**E-Mail ID**	
9886296777		

Zone: DASARAHALLI **Ward No:** 15 **Ward Name:** T Dasarahalli **Street ID:** W0135, W0288, W0124, I0133,

Scanned by CamScanner

Field Inspection Details

Number of Trees	Any Other Information	Name
0		archana
Date of Inspection	**Remarks**	
29/07/2019		

Category	Image	Photo Remark
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Segment End		Location was not determined.
Segment Start		Location was not determined.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	Doddaiah	01/08/2019	29/09/2019	
EE	Jayalingappa BL	31/07/2019	29/09/2019	Completed
AEE	vijaykumar	29/07/2019	29/09/2019	completed
AE	archana	29/07/2019	29/09/2019	completed
AE	archana	29/07/2019	29/05/2019	completed

Zone: DASARAHALLI **Ward No:** 15 **Ward Name:** T Dasarahalli **Street ID:** W0135, W0288, W0124, I0133,

Scanned by CamScanner

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	15	T Dasarahalli
Street ID	**Street Name**	**Significant Landmark**
W0012, W0056, W0052, W0035, W0024, W0033, W0016, W	NA, Om Shakthi Lyt, 9th Crs, 14th Crs, Lakshmi Sagar Lyt, 1st Crs, Kaveri Nagar Near Society Mahade	Dasarahalli
Segment No.	**Total Length (m)**	
15/C-W0012/S032708	2039.32	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	523.81	77.513007	13.043107	77.514460	13.047580	Dasarahalli NH4	Bylappa Circle
2	2.09	77.511395	13.044633	77.511379	13.044622	Dasarahalli	Bylappa Circle
3	142.48	77.510928	13.044424	77.512205	13.044120	Ganesha Saw Mill road	KK Road
4	141.08	77.511014	13.044706	77.512280	13.044413	Ganesha Saw Mill road	KK Road
5	395.53	77.511669	13.047465	77.510762	13.044006	N H 4	Nelamaheshwaramma temple
6	91.71	77.510384	13.046113	77.510130	13.045322	Kempegowda Nagara 3rd cross	2nd Main
7	100.62	77.509262	13.045694	77.510109	13.045322	Kempegowda Nagara 2nd cross	2nd Main
8	91.70	77.509411	13.045975	77.510180	13.045632	Kempegowda Nagara 1st cross	2nd Main
9	91.38	77.509523	13.046223	77.510293	13.045886	Kempegowda Nagara 1st cross	2nd Main
10	91.69	77.509629	13.046519	77.510370	13.046120	Kempegowda Nagara 1st cross	2nd Main
11	367.23	77.508888	13.044965	77.510215	13.048017	Kempegowda Nagara 1st cross	2nd Main

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements of Re Asphalting Dasarahalli Main road and Other roads,S Ramesh, Ganesha saw mill, Kempegowda Nagara & MAheshwari Nagara roads Constructi	30000000	2018-19

Scanned by CamScanner

Year	Type of Work	Other Work Type
2018 - 2019	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Tender		015-18-000007
Work Order No.	**Work Order Date**	**Period of Extention**
305/18-19	02/02/2019	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
19/02/2019	01/02/2020	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M S Venkatesh		21915877.00
Phone No.	**E-Mail ID**	
9886296777		

Field Inspection Details

Number of Trees	Any Other Information	Name
0		archana
Date of Inspection	**Remarks**	
29/07/2019		

Category	Image	Photo Remark
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Segment End		Location was not determined.
Segment Start		Location was not determined.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	Doddaiah	01/08/2019	22/09/2019	

Zone: DASARAHALLI **Ward No:** 15 **Ward Name:** T Dasarahalli **Street ID:** W0012, W0056, W0052, W0035,

Scanned by CamScanner

EE	Jayalingappa BL	31/07/2019	22/09/2019	Completed
AEE	vijaykumar	29/07/2019	22/09/2019	completed
AE	archana	29/07/2019	22/09/2019	completed
AE	archana	29/07/2019	29/05/2019	completed

Zone: DASARAHALLI **Ward No:** 15 **Ward Name:** T Dasarahalli **Street ID:** W0012, W0056, W0052, W0035,

Scanned by CamScanner

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	39	Chokkasandra
Street ID	**Street Name**	**Significant Landmark**
WA268, W0265, W0277, W0267, W0272, W0270, W0266, W	NA, Ambedkar Nagar Slum, Maheshwari Nagar Ambedkar Rd, 1st Crs, Maheshwari Nagar, 2nd A Crs, Maheshw	Ganapathi Temple, Vidyanagara
Segment No.	**Total Length (m)**	
39/C-WA268/S061004	447.96	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	45.42	77.506792	13.041891	77.507210	13.041875	5th A Main Road	SWD
2	25.32	77.506993	13.041598	77.507226	13.041593	5th A Main Road	Deadend
3	34.40	77.507980	13.041389	77.507983	13.041078	5th Cross	Deadend
4	41.08	77.507669	13.041376	77.507656	13.041005	5th Cross	Deadend
5	89.62	77.507299	13.041394	77.508125	13.041407	5th A Main	Deadend
6	76.52	77.507256	13.041663	77.507961	13.041674	5th A Main	Deadend
7	24.44	77.507242	13.041818	77.507468	13.041823	5th A Main	Deadend
8	111.16	77.507226	13.042014	77.507315	13.041015	5th Main Road	SWD

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Construction of Drains and Concrete main Roads and Cross roads of Vidyanagara Dasarahalli Ward No.39, Chokkasandra	5000000	2018
Year	**Type of Work**	**Other Work Type**
2018 - 2019	Others	
Tender	**Work Details**	**Job No. / Work Code**
Tender	0	039-18-000014
Work Order No.	**Work Order Date**	**Period of Extention**
EE/DD/WO/305/2018-19	02/02/2019	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
25/02/2019	24/02/2020	Yes

Scanned by CamScanner

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M S Venkatesh		0.00
Phone No.	**E-Mail ID**	
9886296777		

Field Inspection Details

Number of Trees	Any Other Information	Name
0		chittaiah
Date of Inspection	**Remarks**	
01/08/2019		

Category	Image	Photo Remark
Road Condition		Location was not determined.
Segment End		Location was not determined.
Segment Start		Location was not determined.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	Doddaiah	01/08/2019	03/09/2019	
EE	JAYALINGAPPA	01/08/2019	03/09/2019	
AEE	Thimmegowda	01/08/2019	03/09/2019	
AE	chittiah	01/08/2019	03/09/2019	
AE	CHITTIAH	18/05/2019	26/04/2019	

Zone: DASARAHALLI **Ward No:** 39 **Ward Name:** Chokkasandra **Street ID:** WA268, W0265, W0277, W0267,

Scanned by CamScanner

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	39	Chokkasandra
Street ID	**Street Name**	**Significant Landmark**
W0260	Ambedkar Nagar Slum	Ganapathi Temple
Segment No.	**Total Length (m)**	
39/S-W0260/S055402	224.11	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	224.11	77.508691	13.042052	77.506733	13.042131	5th Main Road	SWD

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Construction of Drain and Concrete Main Roads and Cross roads of Vidyanagara Dasarahalli Ward No.39	5000000	2018
Year	**Type of Work**	**Other Work Type**
2018 - 2019	Road	
Tender	**Work Details**	**Job No. / Work Code**
Tender		039-18-000015
Work Order No.	**Work Order Date**	**Period of Extention**
EE/DD/WO/305/18-19	02/02/2019	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
25/02/2019	24/02/2020	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M S Venkatesh		0.00
Phone No.	**E-Mail ID**	
9886296777		

Scanned by CamScanner

Field Inspection Details

Number of Trees	Any Other Information	Name
0		ramegowda

Date of Inspection	Remarks
01/08/2019	

Category	Image	Photo Remark
Segment End		Location was not determined.
Segment Start		Location was not determined.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	Doddaiah	01/08/2019	03/09/2019	
EE	Jayalingappa	01/08/2019	03/09/2019	
AEE	Thimmegouda	01/08/2019	03/09/2019	
AE	chittaiah	01/08/2019	03/09/2019	
AE	CHITTIAH	18/05/2019	26/04/2019	

Scanned by CamScanner